

# OPTI-SET

(PATENT  
PENDING)

'V'

CE CERT.

THIS "OPTI-SET" SETTING TOOL HAS BEEN CALIBRATED TO MEASURE 40mm WITHIN A TOLERANCE OF  $\pm 0.008m$ .

## TO OPERATE

SWITCH ON / PLACE ONTO DATUM FACE / MOVE TOOL ONTO ANVIL, CONTINUE MOVING TOOL SLOWLY UNTIL THE RED L.E.D. ILLUMINATES / TOOL IS NOW 40MM FROM DATUM / SET / MOVE TOOL AWAY TO RELEASE.

"SWITCH OFF" AFTER USE.

## TO CHANGE BATTERY

"OPTI-SET" HAS A LOW VOLTAGE CUT OUT. WHEN L.E.D. FLASHES REPLACE BATTERY. UNSCREW SLOTTED BATTERY COVER AND REPLACE WITH 6v 160MAH (Px 28L) BATTERY – AVAILABLE FROM R.S. COMPONENTS.